

FT063 - FT064 - FT065


ACU-TEST CABLES FOR FT602




FT Technologies Acu-Test Packs make it easy to test and configure digital wind sensors in a lab or office environment. The Acu-Test Pack for FT602 consists of an Acu-Test cable and the FT Acu-Vis software.

Each cable is labelled with a unique serial number and build date to ensure quality and traceability. For the latest Acu-Vis software, please contact techsupport@fttechnologies.com


FT063 - RS485



FT064 - RS422



FT065 - UART



YOU WILL ALSO NEED



This equipment can be used to test the FT602-D-SM wind sensor. The Acu-Vis software supports Windows XP, Vista, 7, 8, 8.1, 10 and 11.

Warning: Live connection/disconnection of the sensors during live operation could damage the equipment and is not covered by FT's standard warranty terms.

KEEPING IT SIMPLE

This software is to be used as a simple way to test the functionality and change the settings of FT Technologies wind sensors. For full details on Acu-Vis software operation and configuration options, please refer to the FT602 user manual or contact FT Technical Support.

9001820 REV A01

FT Technologies - Sunbury House, Brooklands Close - Sunbury-on-Thames TW16 7DX, United Kingdom sales@fttechnologies.com +44 20 8943 0801

The FT and Acu-Res logos and the Acu-Res® name are registered trade marks of FT Technologies Ltd.

Information furnished by FT Technologies Ltd is believed to be accurate and reliable. However, no responsibility is assumed by FT Technologies for its use; not for any infringements of patents or other rights of third parties which may result from its use. No license is granted by implication or otherwise under any rights of FT Technologies Ltd.

